

Product Safety Recall



YAMAHA FJR1300AE/P Motorcycle 2nd Gear Upgrade

MODEL	MODEL CODE	MODEL YEAR	FRAME NUMBER		
			PREFIX No.	FROM	TO
FJR1300A/E	B966	2016	RP287	000001	000217
	B96A	2017			
	B96C	2018			
	B96G	2019			
	B96R	2020			
FJR1300AP	BK53	2016	RP28B	000001	000223
	BK57	2017			
	BK59	2018			
	BK5F	2019	RP28K	000301	000422
	BK5H	2020			

WHAT ARE THE DEFECTS?

The teeth of the 2nd gear may break due to excessive stress loading during shifting and missed 2nd gear selection resulting in loss of power.

WHAT ARE THE HAZARDS?

If there is a failure to change gears and loss of power while riding, this could increase the risk of an accident or injury or death to rider(s) and/or other road users.

WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected FJR1300 models must have the main & drive axle assembly replaced and ECU reprogrammed.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at <http://www.yamaha-motor.com.au/> or CALL 1300 593 600.

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
other Australian consumer product recalls