

# Product Safety Recall



## YAMAHA FJR1300AE/P Motorcycle Brake Switch

MODEL	MODEL	FRAME NUMBER		
	YEAR	PREFIX No.	FROM	TO
FJR1300A	2013 - 2015	RP234	000003	000237
FJR1300AE	2014 - 2015	RP23H	000001	000052
FJR1300AE	2016 - 2020	RP287	000001	000217
FJR1300AP	2013 - 2015	RP23D	000001	000185
FJR1300PA	2016 - 2018	RP28B	000001	000223
FJR1300PA	2019 - 2020	RP28K	000301	000395

### WHAT ARE THE DEFECTS?

The faulty brake switch can inhibit the cruise control and constantly illuminate the rear brake lights.

### WHAT ARE THE HAZARDS?

If brake lights constantly illuminate, this may give other road users incorrect vehicle signals, increasing the risk of an accident or injury or death to rider(s) and/or other road users.

### WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected models must have the brake switch replaced.

### WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at <http://www.yamaha-motor.com.au/> or CALL 1300 593 600.

**Australian Importer/Distributor**  
**Yamaha Motor Australia**  
489-493 Victoria Street, Wetherill Park  
NSW, Australia

See [www.productsafety.gov.au](http://www.productsafety.gov.au) for  
other Australian consumer product recalls