

Product Safety Recall

Yamaha Waverunner MY2021

VX1050A-W F4N 0800101 - 0803740	VX1050E-W F4N 0800101 - 0803740	VX1800A-W F4S 0800101 - 0803460
		
VX1800C-W F4S 0800101 - 0803461	GP1800A-W F4P 0800101 - 0801740 F4P 0802510 - 0802620	GP1800B-W F4M 0800101 - 0801340 F4M 0801435 - 0801447
		

Sold by Authorised Yamaha dealers between 30 November 2020
and 31 December 2021

Defect A poorly installed sensor in the shut-off switch assembly may allow water to seep inside the sensor (switch housing) and become corroded, causing an intermittent connection.

Hazard An intermittent connection may result in a malfunction with the engine shut-off switch. If the switch malfunctions, the engine may stop suddenly even though the lanyard is in place, or the engine may not stop when the lanyard is pulled. This could result in loss of control of the watercraft and an accident causing injury or death.

What to do When parts become available from June 2021, consumers will be advised to contact their local Yamaha WaveRunner dealership to organise for inspection and repair.

Contact details Consumers can find their nearest authorised Yamaha dealership by visiting <https://www.yamaha-motor.com.au>
For further information, contact Yamaha by phone on 1300 277 137 .

**See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information**