Product Safety Recall



YAMAHA OUTBOARD IGNITION CONTROL SOFTWARE UPDATE

| Primary ID | | | |
|------------|------------|------------|------------|
| 6AL1007281 | 6AL1007291 | 6AL1007315 | 6AL1007332 |
| 6KY1000585 | 6KY1000795 | 6KY1000939 | 6KY1001217 |
| 6KW1001602 | 6LF1002050 | 6LF1003164 | |

Sold by authorised Yamaha dealers between 1 November 2021 to 30 June 2022

Defect

The ignition coils may be energised when the main key switch is turned ON, this is due to improper Engine Control Unit programming.

Hazard

This spark could ignite unburned fuel in the combustion chamber and could damage the Intake Manifold.

What to do

Consumers are requested to contact your local Yamaha Dealer to set up an appointment to have this recall carried out free of charge.

Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting https://www.yamaha-motor.co.nz/

For more information, contact Yamaha Motor New Zealand on 09 265 6500.

Australian Importer/Distributor Yamaha Motor New Zealand 58 Lady Ruby Drive, East Tamaki NSW, New Zealand

See <u>www.recalls.govt.nz/product-safety-alerts</u> for other New Zealand consumer product recalls