

Product Safety Recall



**YAMAHA MY2017 - MY2022 CZD300
YAMAHA MY2020 – MY2022 MWD300
CAMSHAFT RETAINER PLATE BOLD LOOSE**

Defect:

Due to a manufacturing defect, the mounting bolts connecting the camshaft retainer plate may not be sufficiently tightened. As a result, the camshaft retainer plate could become loose causing the engine to stall and fail to restart.

Hazard:

A loss of motive power whilst riding increases the risk of an accident, causing serious injury or death to rider and/or passenger and other road users.

What to do:

Owners of affected vehicles will be contacted by Yamaha, by mail, requesting them to schedule an appointment with their authorised Yamaha Dealer to have the works carried out free of charge.

Contact details:

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at

<http://www.yamaha-motor.co.nz/>

If you no longer own this Motorcycle, please advise Yamaha Motor New Zealand by email

cr@yamaha-motor.com.au

New Zealand Importer/Distributor

Yamaha Motor New Zealand

58 Lady Ruby Drive

East Tamaki

09 265 6500

See www.recalls.govt.nz for
other New Zealand consumer product recalls

Issued: Sept 2025