


# Product Safety Recall



## YAMAHA TMAX Motorcycle Main Stand Breakage

| MODEL | MODEL YEAR | FRAME NUMBER |        |        |
|-------|------------|--------------|--------|--------|
|       |            | PREFIX No.   | FROM   | TO     |
| TMAX  | 2017-2019  | SJ144        | 000001 | 000084 |

### WHAT ARE THE DEFECTS?

The strength of the XP530A main stand may be compromised due to substandard welding at the cross tube.

### WHAT ARE THE HAZARDS?

Repeated operations of the main stand may cause cracking at the weld areas and possible breakage. If the stand was to break and the bike was to fall over, it could cause serious injury to the rider or bystanders.

### WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected XP530A models must have the main stand replaced with one that has been strengthened by increasing the tube thickness and modifying the welding process.

### WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

Contact details: for help finding your nearest authorised dealer call

09 265 6500 or visit the website: <https://www.yamaha-motor.co.nz/>

**Australian Importer/Distributor**  
**Yamaha Motor New Zealand**  
58 Lady Ruby Drive, East Tamaki  
NSW, New Zealand

See <https://www.recalls.govt.nz/product-safety-alerts> for  
other New Zealand consumer product recalls