

# Product Safety Recall



## YAMAHA YXF1000 (R-Max) MY2021

Model name	Model Year	Prefix	Serial
YXF1000	2021	AN39W	300204
YXF1000	2021	AN39W	300217
YXF1000	2021	AN39W	300222
YXF1000	2021	AN39W	300223
YXF1000	2021	AN39W	300224

### Defect

During frame manufacturing, there is a possibility that one or both welds for the Rear Shock Upper Mount Brackets may have been inadvertently missed.

### Hazard

If the inner weld is missing it is possible for the mounting bracket to flex under extended use and fatigue cracking may develop at the outside welds.

### What to do

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

### Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.com.au>

For more information, contact Yamaha Motor Australia on 1300 277 137

**Australian Importer/Distributor**  
**Yamaha Motor Australia**  
489-493 Victoria Street, Wetherill Park  
NSW, Australia

See [www.productsafety.gov.au](http://www.productsafety.gov.au) for  
Australian product recall information