

Product Safety Recall



YAMAHA MY22 YXM700 (Viking) Rear Brake Line

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX No.	FROM	TO
YXM700E	2022	AMA5E	101788	101837
YME700ES	2022	AMB2E	101515	101533

Sold by authorised Yamaha dealers between 1 March 2022 to 30 April 2022

Defect

The retaining clamp for the rear brake pipe may be installed incorrectly.

Hazard

Incorrect installation of the rear brake pipe clamp may cause contact between the rear brake pipe and the front drive shaft leading to wear of the brake pipe and a brake fluid leak, resulting in brake failure. Brake failure during use of a vehicle may cause an accident resulting in serious injury or death of vehicle occupants or bystanders.

What to do

Consumers are requested to contact your local Yamaha Dealer to set up an appointment to have this recall carried out free of charge.

Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.com.au>

For more information, contact Yamaha Motor Australia on 1300 277 137.

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
Australian product recall information