

Product Safety Recall



YAMAHA MY16-21 XV250 SPARK PLUG

MODEL	MODEL CODE	MODEL YEAR	FRAME NUMBER		
			PREFIX No.	FROM	TO
XV250	1BE7,1BE8, 1BE9,1BEA, 1BEB,1BEC	2016-2021	3LVT0	036240	036959

Sold by authorised Yamaha dealers between 1 July 2015 to 31 May 2021

Defect

The motorcycle spark plug does not comply with the [Australian Electromagnetic Compatibility \(EMC\) standards](#), [AS/NZS CISPR 12](#)

Hazard

There is a risk the product may interfere with radio receivers through radio frequency emissions.

What to do

Consumers should contact their local Yamaha dealer to set up an appointment to have the spark plug/s replaced free of charge.

Consumers can find their nearest authorised Yamaha dealer by visiting the [Yamaha webpage](#).

For more information, contact Yamaha Motor Australia by phone 1300 277 137 or [webform](#).

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
Australian product recall information