

Product Safety Recall



YAMAHA F90C Outboard Motor

Affected Serial Number Range 6FP 1000001 ~ 6FP 1002504

Sold nationally at authorised Yamaha Dealers from 23/07/2017

Defect: The bush at the end of the throttle control lever may not have been installed properly at the factory. This may cause the bush to come loose and possible catch on the accelerator cam guide.

Hazard: In the worst case this may result in a loss of engine speed control.

What to do: Contact your local Yamaha Dealer for an appointment to have your **F90C** remedied free of charge.

Contact details: for help finding your nearest authorised dealer call

1300 593 600 or visit the website: <https://www.yamaha-motor.com.au/>

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
other Australian consumer product recalls