

Product Safety Recall



YAMAHA MT03 Motorcycle Primary Driven Gear Exchange

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX No.	FROM	TO
MT03	2017	RH07L	004721	005080

WHAT ARE THE DEFECTS?

A machining defect of the primary drive and driven meshing gears has been determined in the affected models. During acceleration and engine rpm increase when shifting through gear ratios, excessive noise may become evident due to a mismatch of these meshing gear components.

WHAT ARE THE HAZARDS?

The noise generated may exceed the regulated Australian Design Rule (ADR) external noise level standards for this model.

WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected MT03LAH models must have the "Primary Drive Gear" and "Primary Driven Gear Comp." exchanged with a new counter measure one.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

Contact details: for help finding your nearest authorised dealer call

1300 593 600 or visit the website: <https://www.yamaha-motor.com.au/>

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
other Australian consumer product recalls