


Product Safety Recall



YAMAHA MT07/XSR700 Motorcycle Drive Guard Chain Bolt

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX No.	FROM	TO
XSR700L	2016	RM131	000105	000601
	2017	RM131	001101	001520
MT07LA	2018	RM04G	000001	000630
MT07HOAJ	2018	RM04F	000001	000025
MT07RL	2017	RM161	000101	000561

WHAT ARE THE DEFECTS?

The bolt fixing the drive chain guard to the swing arm may loosen due to vibration during riding because of inappropriate design.

WHAT ARE THE HAZARDS?

There is a possibility that the screw may dislodge from the chain guard, allowing it to hit the drive chain and break. In the worst case, the broken part may fall onto the road resulting in a hazard for traffic or other road users.

WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected MT07 & XSR700 models must have the collar and bolt replaced with the countermeasure ones.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

Contact details: for help finding your nearest authorised dealer call

1300 593 600 or visit the website: <https://www.yamaha-motor.com.au/>

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
other Australian consumer product recalls