


# Product Safety Recall



## YAMAHA YZF-R3/MT03 Motorcycle Torsion Spring Breakage

MODEL		FRAME NUMBER	
	PREFIX	FROM	TO
YZF-R3A 2015 ~ 2016			
MT03LA 2016	RH072	001001	004400
	RH07L	001001	001760

### WHAT IS THE DEFECT?

Due to a broken shift mechanism torsion spring, riders may not be able to select the desired gear.

### WHAT ARE THE HAZARDS?

Inability to shift gears properly resulting in difficulty in manoeuvring the vehicle while riding.

### WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected models must have the shift mechanism torsion spring exchanged with a new counter measure one.

### WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

Contact details: for help finding your nearest authorised dealer call

1300 593 600 or visit the website: <https://www.yamaha-motor.com.au/>

**Australian Importer/Distributor**  
**Yamaha Motor Australia**  
489-493 Victoria Street, Wetherill Park  
NSW, Australia

See [www.productsafety.gov.au](http://www.productsafety.gov.au) for  
other Australian consumer product recalls