

Product Safety Recall



YAMAHA PORTABLE GENERATOR EF2000iS

Affected Range

7PB 0329803 ~ 7PB 0330916 - 2018

7PB 5080473 ~ 7PB 5080496 - 2019

CORRECTIVE ACTION FOR FUEL TANK CRACKING

DEFECT The molded area of the fuel tank to which the fuel valve is mounted was molded at the incorrect temperature.

HAZARDS The tank material can be too brittle allowing the tank to crack. If the fuel tank cracks, fuel could leak increasing the risk of fire, which could result in severe injury or death.

REMEDY Yamaha recommends that consumers do not operate their affected generator until this modification is performed. The Yamaha retailer will replace the fuel tank with one that has been correctly molded. For details of your local retailer please call **1300 735 440** or visit www.generator-yamaha.com.au/where-to-buy/

**See productsafety.gov.au for
Australian product recall information**