

Product Safety Recall



YAMAHA MY21/22 MT09 & MT09TRA Limited Throttle Response/Engine Stall

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX No.	FROM	TO
MTN890	2021-2022	RN692	000301	001043
MTN890D	2021-2022	RN696	000301	000656
MTT890D	2021-2022	RN706	000301	000560

Sold by authorised Yamaha dealers between 1 November 2020 to 31 January 2022

Defect

Due to a software fault in the vehicle's Electronic Control Unit (ECU) the engine may stall resulting in an unexpected loss of vehicle control accompanied by a warning light on the instrument panel.

Hazard

The incorrect ECU program can cause unexpected engine stalling, poor performance and engine lights to be displayed.

What to do

Consumers are requested to contact your local Yamaha Dealer to set up an appointment to have this recall carried out free of charge.

Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.co.nz/>

For more information, contact Yamaha Motor New Zealand on 09 265 6500.

Australian Importer/Distributor
Yamaha Motor New Zealand
58 Lady Ruby Drive, East Tamaki
NSW, New Zealand

See www.recalls.govt.nz/product-safety-alerts for
other New Zealand consumer product recalls