

Product Safety Recall



YAMAHA MY2021-MY2024 MT09 TRACER ECU REPROGRAM & TPS REPLACEMENT.

Defect:

Due to a manufacturing issue, the throttle position sensor may be faulty. This may lead to unstable engine idling and possible stalling resulting in a loss of motive power.

Hazard:

A loss of motive power whilst riding increases the risk of an accident, causing serious injury or death to rider and/or passenger and other road users.

What to do:

Owners of affected vehicles will be contacted by Yamaha, by mail, requesting them to schedule an appointment with their authorised Yamaha Dealer to have the works carried out free of charge.

Contact details:

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at

<http://www.yamaha-motor.com.au/> or CALL 1300 277 137.

If you no longer own this Motorcycle, please advise Yamaha Motor Australia on 1300 277 137 or email

cr@yamaha-motor.com.au

**Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia**

See www.productsafety.gov.au for
other Australia consumer product recalls

Issued: Feb 2025