



Product Safety Recall



Do you own this product?

Yamaha Golf Car

G29 2/4-Seater or UMX (Utility)

Dates sold: G29 (2016-2023) /

Utility (2016-2022)



Why the product is recalled: The accelerator pedal return spring may break during use and the accelerator pedal may not return when released.

Hazard: Risk of serious injury from collision if the accelerator pedal doesn't return when released and the vehicle doesn't slow down as expected. At least 1 incident has occurred because of this defect.



Stop using these vehicles and check if the golf car is affected. Contact your local Yamaha dealer to arrange for a free repair.

Send us an email if you are unable to return the product due to it being sold or gifted it to another person cr@yamaha-motor.com.au



If you need help finding a Yamaha Dealer in your area, simply visit us on the web at <http://www.yamaha-motor.com.au/> or CALL 1300 277 137.



Purchased from: Authorised Yamaha Dealers



Scan the QR code for a link to Yamaha's website

Australian Importer/Distributor, Yamaha Motor Australia

489-493 Victoria Street, Wetherill Park, NSW, Australia

See productsafety.gov.au for
Australian product recall information