

# Product Safety Recall



## YAMAHA MY2021 MT09 Tracer Throttle Sticking

MODEL	MODEL CODE	MODEL YEAR	FRAME NUMBER		
			PREFIX NO.	FROM	TO
MTT890D	BAP8	2021	RN706	0000301	0000502

Sold by authorised Yamaha dealers between 1 February 2021 to 1 September 2021

### Defect

Excessive clearance between the Throttle Tube and End Grip may result in the Throttle Tube breaking if excessive lateral pulling force is applied.

### Hazard

Breakage at the throttle tube may cause the throttle grip to catch (stick) or restrict throttle movement, resulting in possible excess speed and/or potential to cause injury to the rider or passenger.

### What to do

Consumers are requested to contact your local Yamaha Dealer to set up an appointment to have this recall carried out free of charge.

### Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.co.nz/>

For more information, contact Yamaha Motor New Zealand on 09 265 6500.

**Australian Importer/Distributor**  
**Yamaha Motor New Zealand**  
58 Lady Ruby Drive, East Tamaki  
NSW, New Zealand

See [www.recalls.govt.nz/product-safety-alerts](https://www.recalls.govt.nz/product-safety-alerts) for  
other New Zealand consumer product recalls