


Product Safety Recall



YAMAHA YZF-R3/MT03 Motorcycle Brake Level Failure

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX NO.	FROM	TO
MT03	2019	RH127	002041	002080
YZF-R3	2019	RH12H	001081	001200

WHAT ARE THE DEFECTS?

There is a potential for the Front Brake “Lever 2” to break when strong gripping force is applied on affected YZF-R3 & MT03 Models.

WHAT IS THE REMEDY?

Yamaha is replacing the brake lever with countermeasure parts on any affected units with a specific stamping code.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model inspected and/or remedied free of charge.

Contact details: for help finding your nearest authorised dealer call

1300 593 600 or visit the website: <https://www.yamaha-motor.com.au/>

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
other Australian consumer product recalls