

IMPORTANT NOTICE

MW125 *Tricity* Vehicle Standards Exemption

Owner Name.....

Address.....

Dear Owner,

It has been identified that the MW125 *Tricity* was certified for entry into service without having a parking brake as required by Land Transport Rule: Light-vehicle Brakes 2002.

Yamaha Motor New Zealand applied for an exemption to the requirement and demonstrated to the NZ Transport Agency that the front end is like that of a motorcycle, ie not fixed and it will fall over when not supported.

The NZ Transport Agency agreed that the risk to safety is minimised and an exemption was issued. A requirement of the exemption is to fit a label on each scooter to inform WoF inspectors.

Your urgent attention is required concerning this NZTA Vehicle Category compliance of your road registered *Tricity*.

The Exemption Label, displaying the NZTA Approval Number, must be attached to the inside wall of the storage compartment as illustrated below and must be visible to W.o.F certified inspectors or NZTA examiners in the event of an inspection.

You are required to present your MW125 *Tricity* to the service manager of your nearest Yamaha Dealership to have the Exemption label applied immediately.

The affixing of this approved Exemption Label will ensure your vehicle is not in breach of the New Zealand Vehicle Standards Regulations and allowed be operated as normal.

Thank you for purchasing the Yamaha MW125 *Tricity* and for your immediate attention in this correction program.

The Management

Yamaha Motor New Zealand Ltd

All MW125 *Tricity* scooters must display the label below...

