

# Product Safety Recall



## YAMAHA NMAX Motorcycle Non-Compliant Rear Reflector

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX	FROM	TO
NMAX – 125	2015	SE935	001001	003840
NMAX - 150	2017-2020	SG432	001001	001640

### WHAT IS THE DEFECT?

The “REAR REFLECTOR ASSY” on the listed model, may not comply with UN-ECE standard specification for reflection luminosity.

### WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected models must have the defective “REAR REFLECTOR ASSY” replaced with the countermeasure one.

### WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at

<http://www.yamaha-motor.com.au/> or CALL 1300 593 600.

If you no longer own the unit, please advise Yamaha Motor Australia on 1300 593 600.

**Australian Importer/Distributor**  
**Yamaha Motor Australia**  
489-493 Victoria Street, Wetherill Park  
NSW, Australia

See [www.productsafety.gov.au](http://www.productsafety.gov.au) for  
other Australian consumer product recalls