


Product Safety Recall



YAMAHA XMAX Motorcycle Non-Compliant Rear Reflector

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX	FROM	TO
XMAX	2017-2020	SH084	001001	011130

WHAT IS THE DEFECT?

The “REAR REFLECTOR ASSY” on the listed model, may not comply with UN-ECE standard specification for reflection luminosity.

WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected models must have the defective “REAR REFLECTOR ASSY” replaced with the countermeasure one.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at

<http://www.yamaha-motor.com.au/> or CALL 1300 593 600.

If you no longer own the unit, please advise Yamaha Motor Australia on 1300 593 600.

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
other Australian consumer product recalls