

# Product Safety Recall



## YAMAHA MT03 Motorcycle Non-Compliant Rear Reflector

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX	FROM	TO
MT03	2016-2017	RH07L	001001	005800
	2018-2019	RH127	001001	002640
	2020	RH12R	001001	001440

### WHAT IS THE DEFECT?

The “REAR REFLECTOR ASSY” on the listed model, may not comply with UN-ECE standard specification for reflection luminosity.

### WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected models must have the defective “REAR REFLECTOR ASSY” replaced with the countermeasure one.

### WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at

<https://www.yamaha-motor.co.nz/> or CALL 09 265 6500.

**Australian Importer/Distributor**  
**Yamaha Motor New Zealand**  
58 Lady Ruby Drive, East Tamaki  
NSW, New Zealand

See <https://www.recalls.govt.nz/product-safety-alerts> for  
other New Zealand consumer product recalls